

# Annexure D

## BUILDING SAFETY CERTIFICATE

No. 234/28

Dated: 22/03/25

It is certified that the existing building **Royal International School, Odisha** (name of the building or premises) At- Anata, Po- Jayanagar Ps-Jeypore, Dist-Koraput ,Odisha (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+2	G+1				

The building is owned/occupied by **ROYAL INTERNATIONAL SCHOOL** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **R&B Sub-Division, Jeypore** (Name of Department/Govt.) on **15/02/2025** (date of inspection) in the presence of **Sweta Praharaj**, Jeypore (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **22/02/2025** for a period of **03** years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1. Structural Safety Foundation is structurally sound and shows no signs of subsidence. Load-bearing walls are free from cracks or deterioration.**
- 2. Fire Safety Fire extinguishers are installed and functional in all key areas. Fire exit signs are clearly marked.**
- 3. Electrical Safety Wiring is properly insulated and concealed. Main electrical panels are installed in a Secure room**

Issued on **22/02/2025** at **Anata** by

*[Signature]*  
22/03/25

Asst. Executive Engineer  
Jeypore (R&B) Sub-Division  
Asst. Executive Engineer  
R&B Sub-Division  
Jeypore